

Street	Cross Street Name	Owned	Maint.	Controller	Cost	Comm equip	Cost	Cabinet	Cost	Optimization	cost	Data Collection	Cost	Transuite	cost	Conversion	cost	Testing Requirements	Tech	
185th Ave	West Union	Washington County	Washington County	2070	3530	GDI 2070-6A	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Westview HS	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Rock Creek Rd	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1, Econolite GPS-100	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Bronson	ODOT	ODOT	2070	3530	GDI 2070-6B, 30-40 US Robotics 56K standalone modem #USR56896E, Econolite GPS-100	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
185th Ave	US 26 - WB Ramps	ODOT	ODOT	2070	3530	GDI 2070-6B	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
185th Ave	US 26 - EB Ramps	ODOT	ODOT	2070	3530	GDI 2070-6B	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
185th Ave	Evergreen Pkwy	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Town Center	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Cornell	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Elder	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Sunset Square	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Walker	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Par Lumber	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Heritage Pkwy	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Salix	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Baseline	Washington County	Washington County	2070	3530	GDI 2070-6A, RuggedCom RS930L-HI-N-V1-V1, Econolite GPS-100	3617.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Stepping Stone	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1, Econolite GPS-100	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Johnson	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	TV Hwy - ORE 8	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9			Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
185th Ave	Kinnaman	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Rosa	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
185th Ave	Farmington - ORE 10	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
010th Ave	TV Hwy - ORE 8	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9			Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
010th Ave	Washington	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	Main St	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	Grant	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	Arrington	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1, Econolite GPS-100	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	025th Ave	Washington County	Washington County	2070	3530	Econolite GPS-100	1265	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	034th Ave	Washington County	Washington County	2070	3530	Econolite GPS-100	1265	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	Brookwood Pkwy	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	3617.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	048th Ave	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	Elam Young (West)	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	Shute Rd	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	Elam Young (East)	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	Orencia Station	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	231st	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	Walbridge	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	Butler	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1, Econolite GPS-100, GDI 2070-7A	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Cornell Rd	Cornelius Pass Rd	Washington County	Washington County	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	Laurelwood	Washington County	Beaverton	2070	3530	GDI 2070-7A	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	Allen Blvd	Washington County	Beaverton	2070	3530	GDI 2070-7A	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	Denney	Washington County	Beaverton	2070	3530	GDI 2070-7A	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	Hall Blvd	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	Yes	12800	Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
Scholls Ferry Rd	NB Ramp	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	Yes	12800	Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
Scholls Ferry Rd	NB Ramp	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	Yes	12800	Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
Scholls Ferry Rd	SB Ramp	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	Yes	12800	Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
Scholls Ferry Rd	Cascade	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	Yes	12800	Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
Scholls Ferry Rd	Nimbus	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	Conestoga	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	121st Ave	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	125th Ave	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	130th Ave	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	135th Ave	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	Davies Rd	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	Murray Blvd	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1, Econolite GPS-100, GDI 2070-7A	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	147th Ave	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	Teal	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	Blackbird	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	Barrows (West)	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
Scholls Ferry Rd	Roy Rogers	Washington County	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
SE Johnson Creek Bl	SE Fuller Rd	Clackamas County	Clackamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1	2403.5	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
SE Johnson Creek Bl	I-205 SB ramps	Clackamas County	Clackamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1	2403.5	No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in		600
SE Johnson Creek Bl	I-205 NB ramps	Clackamas County	Clackamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1	2403.5	No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in		600
SE Johnson Creek Bl	SE 92nd Ave	Clackamas County	Clackamas County	2070	3530	RuggedCom RS900L-HI-D-C2-C2-V1	2403.5	No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in		600
SE Otty Rd	SE Fuller Rd	Clackamas County	Clackamas County	2070	3530	Serial modem	506	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
SE Otty Rd / Idleman	SE 92nd Av / Bob Schumacher	Clackamas County	Clackamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1	2403.5	No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in		600
SE Bob Schumacher	SE Causey Av	Clackamas County	Clackamas County	2070	3530	nothing		No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in		600
SE Monterey Av	SE 85th Av	Clackamas County	Clackamas County	2070	3530	nothing		No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in		600

Street	Cross Street Name	Owned	Maint.	Controller	Cost	Comm equip	Cost	Cabinet	Cost	Optimization	cost	Data Collection	Cost	Transuite	cost	Conversion	cost	Testing Requirements	Tech	
SE Monterey Av	SE Bob Schumacher Rd	Clickamas County	Clickamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1	2403.5	No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in		600
SE Stevens Rd	SE Bob Schumacher Rd	Clickamas County	Clickamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1	2403.5	No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in		600
SE Stevens Rd	Gramor Access	Clickamas County	Clickamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1	2403.5	No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in		600
SE Harmony Rd	Aquatic Ctr	Clickamas County	Clickamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1	2403.5	No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in		600
SE Harmony Rd	SE Fuller Rd	Clickamas County	Clickamas County	2070	3530	RuggedCom RS900L-HI-D-C2-C2-V1	2403.5	No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in		600
SE Sunnyside Rd	8600 Block	Clickamas County	Clickamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1	2403.5	No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	9000 Block	Clickamas County	Clickamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1	2403.5	No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	SE 93rd Av	Clickamas County	Clickamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1, RuggedCom RS900-HI-D-C2-C2-00	2403.5	No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	I-205 SB ramps	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No						yes	500	Yes	750	Chamber testing, timing burn in	1000	600
SE Sunnyside Rd	I-205 NB ramps	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No						yes	500	Yes	750	Chamber testing, timing burn in	1000	600
SE Sunnyside Rd	SE 97th Av (Comm Hub)	Clickamas County	Clickamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1, RuggedCom RS900-HI-D-C2-C2-00	4174.5	No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	SE Stevens Rd	Clickamas County	Clickamas County	2070	3530	RuggedCom RS900L-HI-D-C2-C2-V1	2403.5	No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	SE 101st Av	Clickamas County	Clickamas County	2070	3530	RuggedCom RS930L-HI-D-V1-V1, RuggedCom RS900-HI-D-C2-C2-00		No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	SE 105th Dr	Clickamas County	Clickamas County	2070	3530	nothing		No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	SE Sunnybrook Blvd	Clickamas County	Clickamas County	2070	3530	nothing		No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	SE Valley View Ter	Clickamas County	Clickamas County	2070	3530	nothing		No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	SE 117th Av	Clickamas County	Clickamas County	2070	3530	nothing		No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	SE 119th Dr	Clickamas County	Clickamas County	2070	3530	nothing		No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	SE 122nd Av	Clickamas County	Clickamas County	2070	3530	nothing		No						yes	500	Yes	750	Chamber testing, timing burn in		600
SE Sunnyside Rd	SE 132nd Av	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500					no		600
SE Sunnyside Rd	SE 142nd Av	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500					no		600
SE Sunnyside Rd	SE 147th Av	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500					no		600
SE Sunnyside Rd	SE 152nd Av	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500					no		600
SE Sunnyside Rd	SE 157th Av	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500					no		600
SE Sunnyside Rd	SE 162nd Av	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500					no		600
SE Sunnyside Rd	SE 172nd Av	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500					no		600
SE Sunnybrook Blvd	SE 84th Av	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500					no		600
SE Sunnybrook Blvd	8700 Block (Middle)	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500					no		600
SE Sunnybrook Blvd	SE Oak Bluff Rd	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500					no		600
SE Sunnybrook Blvd	SE 93rd Av	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500					no		600
SE Sunnybrook Blvd	I-205 SB ramps	ODOT		2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in	1000	600
SE Sunnybrook Blvd	I-205 NB ramps	ODOT		2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500	yes	500			Chamber testing, timing burn in	1000	600
SE Sunnybrook Blvd	SE 97th Av	Clickamas County	Clickamas County	no		nothing		No		Yes	2500	Yes	1500	yes	500			no		600
N Frontage Rd	Marine Dr	ODOT	ODOT	2070	0	RuggedCom RS930L-HI-N-V1-V1	3289	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
S Fontage Rd	Marine Dr	ODOT	ODOT	2070	0	RuggedCom RS930L-HI-N-V1-V1	3289	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
N Frontage Rd	Graham Rd (257th)	ODOT	ODOT	2070	0	RuggedCom RS930L-HI-N-V1-V1	3289	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
S Fontage Rd	Graham Rd (257th)	ODOT	ODOT	2070	0	RuggedCom RS930L-HI-N-V1-V1	3289	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
NW Graham Rd	257th Way (Outlets)	Multnomah	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
SW 257th Dr	Columbia River Hwy	Multnomah	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
SW 257th Dr	Cherry Pk Rd (N)	Multnomah	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	Yes	12800	Yes	2500	Yes	1500					Chamber testing, timing burn in		600
SW 257th Dr	Cherry Pk Rd (S)	Multnomah	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	Yes	12800	Yes	2500	Yes	1500					Chamber testing, timing burn in		600
SW 257th Dr	Hensley Rd	Multnomah	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
NE Kane Rd	SE Stark St	Gresham	Gresham/Multnomah	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	Yes	12800	Yes	2500	Yes	1500					Chamber testing, timing burn in		600
NE Kane Rd	NE 29th St	Gresham	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
NE Kane Rd	NE 23rd St	Gresham	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	Yes	12800	Yes	2500	Yes	1500					Chamber testing, timing burn in		600
NE Kane Rd	NE 17th St	Gresham	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	Yes	12800	Yes	2500	Yes	1500					Chamber testing, timing burn in		600
NE Kane Rd	NE Division St	Gresham	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	Yes	12800	Yes	2500	Yes	1500					Chamber testing, timing burn in		600
NE Kane Rd	Fire Station 72	Gresham	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No										Chamber testing, timing burn in		600
SE Kane Rd	SE 1st St	Gresham	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
SE Kane Rd	Powell Valley Rd	Gresham	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
SE Kane Rd	SE 11th St	Gresham	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
SE Kane Rd	SE Palmquist Rd	Gresham	Gresham	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	yes	1500					Chamber testing, timing burn in		600
Mt Hood Hwy	SE Palmquist Rd	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
SE Stark St	SW Sundial Ave	Gresham	Gresham/Multnomah	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
SE Stark St	NE Hale Ave	Gresham	Gresham/Multnomah	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	No		Yes	2500	Yes	1500					Chamber testing, timing burn in		600
TV Hwy	Camelot Ct	ODOT	ODOT	2070	3530	GDI 2070-6B, 30-40 US Robotics 56K standalone modem #USR56896E	1012	no		yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	Canyon Ln, Hwy 29, MP0.3	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	87th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B, 30-40 US Robotics 56K standalone modem #USR56896E	1012	no		yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	91st Ave	ODOT	ODOT	2070	3530	GDI 2070-6B, 30-40 US Robotics 56K standalone modem #USR56896E	1012	yes	12800	yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	Walker Rd, Hwy	ODOT	ODOT	2070	3530	GDI 2070-6B, 30-40 US Robotics 56K standalone modem #USR56896E	1012	no		yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	185th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes	12800	yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	198th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		2009								Chamber testing, timing burn in		600
TV Hwy	205th Ave / Intel Access	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		2009								Chamber testing, timing burn in		600
TV Hwy	209th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes	12800	2009								Chamber testing, timing burn in		600
TV Hwy	Cornelius Pass Rd/219th A	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		2009								Chamber testing, timing burn in		600
TV Hwy	229th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B, 30-40 US Robotics 56K standalone modem #USR56896E	1012	no		2009								Chamber testing, timing burn in		600
TV Hwy	234th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		2009								Chamber testing, timing burn in		600
TV Hwy	Brookwood	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		2009								Chamber testing, timing burn in		600

Street	Cross Street Name	Owned	Maint.	Controller	Cost	Comm equip	Cost	Cabinet	Cost	Optimization	cost	Data Collection	Cost	Transuite	cost	Conversion	cost	Testing Requirements	Tech	
TV Hwy	Sunset Esplanade West	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes	12800	yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	Sunset Esplanade E/24th	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes	12800	yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	Minter Bridge/Cypress St	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	River Rd / 13th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B, 30-40 US Robotics 56K standalone modem #USR56896E	1012	yes	12800	yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	Shute Plaza / Center	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	Maple St	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	Walnut St	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	Oak St	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	Baseline Rd/10th	ODOT	ODOT	2070	3530	GDI 2070-6B	506	no		yes	2500	yes	1500					Chamber testing, timing burn in		600
TV Hwy	7th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	8th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B, 30-40 US Robotics 56K standalone modem #USR56896E	1012	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	7th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	5th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	5th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	3rd Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	3rd Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	1st Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	2nd Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	1st Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	Dennis Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	Dennis Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	Main St	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	17th Ave	ODOT	ODOT	2070	3530	GDI 2070-6B	506	yes, 336	12800							yes	750	Chamber testing, timing burn in		600
TV Hwy	107	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	Yes	12800			N (10/07)				yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	110	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no				N (10/07)				yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	217 E	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no				N (10/07)				yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	217 W	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no				N (10/07)				yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	115	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no				N (10/07)				yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	117	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no				N (10/07)				yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	Lombard	ODOT	Beaverton	NO		RuggedCom RS930L-HI-N-V1-V2	2352.9	no								yes	750			600
TV Hwy	Lombard	ODOT	Beaverton	NO		RuggedCom RS930L-HI-N-V1-V3	2352.9	no												600
TV Hwy	Hall	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	yes	12800			N (10/07)				yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	Watson	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	yes	12800			N (10/07)				yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	Cedar Hills	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	yes	12800			N (10/07)				yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	Hocken	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	yes	12800			N (10/07)				yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	Murray	ODOT	Beaverton	2070	3530	nothing		no								yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	153rd	ODOT	Beaverton	2070	3530	nothing		no								yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	160th/Millikan	ODOT	Beaverton	2070	3530	nothing		no								yes	750	Chamber testing, timing burn in	1000	600
TV Hwy	170th	ODOT	Beaverton	2070	3530	nothing		no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Lindy Lane	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	no		yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	Johnson Cr	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	no		yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	Overland St	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	no		yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	Otty Road	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	no		yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	King Rd	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	yes	12800	yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	Boyer Dr	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	yes	12800	yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	Causey Ave	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	yes	12800	yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	Monterey Ave	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	no		yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	North Town Center Access	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	no		yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	South Town Center Access	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	no		yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	Sunnyside/Harmony Rd	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	no		yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	Sunnybrook	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	no		yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	Killingsworth	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem	278.3	no		yes	2500	yes	1500	yes	500			Chamber testing, timing burn in	1000	600
82nd	Webster	ODOT	PBOT	2070	3530	Netsys NV-600L VDSL2 CO Modem, Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Prescot	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600R VDSL2 CPE modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Sandy	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600L VDSL2 CO Modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Fremont	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600R VDSL2 CPE modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Siskiyou	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Madison High	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600L VDSL2 CO Modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Tillamook	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600R VDSL2 CPE modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Jonesmore	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Wasco	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Multnomah	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600L VDSL2 CO Modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Glisan	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	278.3	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Burnside	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600R VDSL2 CPE modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Davis	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	1070.19	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Stark	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600L VDSL2 CO Modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Washington	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Yamhill	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600R VDSL2 CPE modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600

Street	Cross Street Name	Owned	Maint.	Controller	Cost	Comm equip	Cost	Cabinet	Cost	Optimization	cost	Data Collection	Cost	Transuite	cost	Conversion	cost	Testing Requirements	Tech	
82nd	Mill	ODOT	PBOT	2070	3530	2 each Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Linksys Etherfast EZXS55W 1	1027.18	yes	12800							yes	750	Chamber testing, timing burn in	1000	600
82nd	Division	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600L VDSL2 CO Modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Woodward	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600R VDSL2 CPE modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Powell	ODOT	PBOT	2070	3530	2 each Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Linksys Etherfast EZXS55W 1	1027.18	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Boise	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600L VDSL2 CO Modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Holgate	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Raymond	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Foster	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Woodstock	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Duke	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600R VDSL2 CPE modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Flavel	ODOT	PBOT	2070	3530	Etherwan 10/100TX Industrial Ethernet Extender PN# ED3101-2PK, Netsys NV-600L VDSL2 CO Modem	791.89	no								yes	750	Chamber testing, timing burn in	1000	600
82nd	Springwater Trail	ODOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem	278.3	no								yes	750	Chamber testing, timing burn in	1000	600
Sandy	8th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem	278.3	no								yes	750	Chamber testing, timing burn in		600
Sandy	12th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	16th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	18th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	20th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	22nd	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	24th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	28th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	33rd	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	37th	PBOT	PBOT	2070	3530	Netsys NV-600L VDSL2 CO Modem	278.3	no								yes	750	Chamber testing, timing burn in		600
Sandy	39th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	39th at Broadway	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	39th at Hasslo	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	39th at Halsey	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	40th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	41st	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	42nd at Hancock	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	42nd at Broadway	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	Halsey at I-84 off ramp	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	39th at I-84	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	42nd and Halsey	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	42nd	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	43rd	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	47th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	50th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	52nd	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	54th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	57th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	62nd	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	67th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	70th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	72nd	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem	278.3	no								yes	750	Chamber testing, timing burn in		600
Sandy	77th	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem	278.3	no								yes	750	Chamber testing, timing burn in		600
Sandy	82nd	PBOT	PBOT	2070	3530	Netsys NV-600L VDSL2 CO Modem	278.3	no								yes	750	Chamber testing, timing burn in		600
Sandy	87th	PBOT	PBOT	2070	3530	N/A		no								yes	750	Chamber testing, timing burn in		600
Sandy	Prescott	PBOT	PBOT	2070	3530	Netsys NV-600R VDSL2 CPE Modem, Netsys NV-600L VDSL2 CO Modem	556.6	no								yes	750	Chamber testing, timing burn in		600
Sandy	96th	PBOT	PBOT	2070	17650	5 each Netsys NV-600R VDSL2 CPE Modem, 5 each Netsys NV-600L VDSL2 CO Modem	2783	no								yes	750	Chamber testing, timing burn in		600
Barbur	Hamilton	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	Miles	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	Terwilliger	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	Bertha	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	19th	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	24th	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	30th	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	Park and Ride	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	Taylor's Ferry	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	Capitol	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	Huber	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	I-5 NB	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	Taylor's Ferry/Troy	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	Galeburn	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
Barbur	SW Ramona	ODOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in	1000	600
BH Hwy	Terwilliger	PBOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in		600
BH Hwy	Sunset	PBOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in		600
BH Hwy	Capitol Highway	PBOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in		600
BH Hwy	Vermont	PBOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in		600

Street	Cross Street Name	Owned	Maint.	Controller	Cost	Comm equip	Cost	Cabinet	Cost	Optimization	cost	Data Collection	Cost	Transuite	cost	Conversion	cost	Testing Requirements	Tech	
BH Hwy	13th	PBOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in		600
BH Hwy	25th	PBOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in		600
BH Hwy	30th	PBOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in		600
BH Hwy	39th	PBOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in		600
BH Hwy	45th	PBOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in		600
BH Hwy	Shattack	PBOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in		600
BH Hwy	56th	PDOT	PBOT	2070	3530	GDI 2070-6B	632.5	no								yes	750	Chamber testing, timing burn in		600
BH Hwy	White Pine	ODOT	ODOT	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2403.5	no		yes	2500	yes	1500					Chamber testing, timing burn in	1000	600
BH Hwy	78th Ave	ODOT	ODOT	2070	3530	nothing		no								yes	750	Chamber testing, timing burn in	1000	600
BH Hwy	Scholls/Oleson	ODOT	ODOT	2070	3530	GDI 2070-6A, 30-40 US Robotics 56K standalone modem #USR56896E	1012	no								yes	750	Chamber testing, timing burn in	1000	600
BH Hwy	217 W Ramp	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no		N (10/07)						yes	750	Chamber testing, timing burn in	1000	600
BH Hwy	217 E Ramp	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no		N (10/07)						yes	750	Chamber testing, timing burn in	1000	600
BH Hwy	110th	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no		N (10/07)						yes	750	Chamber testing, timing burn in	1000	600
BH Hwy	107th	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no		N (10/07)						yes	750	Chamber testing, timing burn in	1000	600
BH Hwy	Western	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no		N (10/07)						yes	750	Chamber testing, timing burn in	1000	600
BH Hwy	Jamieson	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no		Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
BH Hwy	91st	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no		Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
BH Hwy	Laurelwood	ODOT	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	2352.9	no		Yes	2500	Yes	1500					Chamber testing, timing burn in	1000	600
Allen	Bus barn	Beaverton	Beaverton	2070	3530	nothing	2352.9	no								yes	750	Chamber testing, timing burn in		600
Allen	Western	Beaverton	Beaverton	2070	3530	nothing	2352.9	no								yes	750	Chamber testing, timing burn in		600
Allen	Arctic Dr	Beaverton	Beaverton	2070	3530	nothing	2352.9	no								yes	750	Chamber testing, timing burn in		600
Allen	Wilson	Beaverton	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	632.5	no		yes	2500	Yes	1500			yes	750	Chamber testing, timing burn in		600
Allen	Menlo	Beaverton	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	632.5			yes	2500	Yes	1500			yes	750	Chamber testing, timing burn in		600
Allen	Erickson	Beaverton	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	632.5	Yes	12800	yes	2500	Yes	1500			yes	750	Chamber testing, timing burn in		600
Allen	Main St	Beaverton	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	632.5	yes	12800	yes	2500	Yes	1500			yes	750	Chamber testing, timing burn in		600
Allen	Hall	Beaverton	Beaverton	2070	3530	RuggedCom RS930L-HI-N-V1-V1	632.5	yes	12800	yes	2500	Yes	1500			yes	750	Chamber testing, timing burn in		600